



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Aug 21, 2024 14:53
Num. 848fc71 - Pág. 1



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Ass 21, 2024, 14:53
Num. 848fc71 - Pág. 2



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647


Assinado eletronicamente por: FRED HENRIQUE OLIVEIRA DA SILVA - Juntado em: 22/08/2024 18:39:20 - 848fc71





Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Assinado eletronicamente por: FRED HENRIQUE OLIVEIRA DA SILVA - Juntado em: 22/08/2024 18:39:20 - 848fc71
Num. 848fc71 - Pág. 5



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Assinado eletronicamente por: FRED HENRIQUE OLIVEIRA DA SILVA - Juntado em: 22/08/2024 18:39:20 - 848fc71
Num. 848fc71 - Pág. 6

áquinas

linas, peças e assistência

91-2232

3138-7064



321C-131M-04

CAT NO

THE SING

SERIAL NO 1753355

Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA

<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>

Número do documento: 24082218342496100000066260647

Num. 848fc71 - Pág. 7



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Aug 21, 2024 14:53
Num. 848fc71 - Pág. 8



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Num. 848fc71 - Pag. 9

交流伺服控制系统

AC SERVO CONTROL SYSTEM

额定电压：AC220V

额定功率：550W

频率：50/60Hz

最大转速：5500RPM

Rated Voltage: AC 220V

Rated Power: 550W

Frequency: 50 / 60Hz

Max Speed: 5500RPM




危险

WARNING

1. 伺服驱动器必须接地，否则有触电危险。
2. 伺服驱动器严禁接入超过250V电压的电源。
3. 严禁打开驱动器和电机的后盖。
4. 使用前请详细阅读说明书。
5. 严禁塑料外壳受力及受压。

1. Servo driver must connect to earth wire, otherwise will cause risk of electric shock.
2. Servo driver is strictly prohibited to connect with power over than 250 V voltage.
3. Prohibit to open the front and rear cover of the driver and motor.
4. Please read instructions carefully before use.
5. Prohibit plastic shell being applied heavy objects or excessive force.



警告

CAUTION

不要触摸零件。
在有安全设施下进行操作。
在穿线、换线、机针及薄口等之
前先关电源停止转动。
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
wiring, changing bobbin and

JACK 杰克

Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA.

<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>


Número do documento: 24082218342496100000066260647

Aug 21, 2024, 14:56
Num. 848fc71 - Pág. 10



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Num. 848fc71 - Pág. 11



交流伺服控制系统

AC SERVO CONTROL SYSTEM

额定电压: AC220V

频率: 50/60Hz

Rated Voltage: AC 220V

Frequency: 50 / 60Hz

额定功率: 550W

最大转速: 5500RPM


Rated Power: 550W

Max Speed: 5500RPM



危险 WARNING

1. 伺服驱动器必须接地, 否则有触电危险。
 2. 伺服驱动器严禁接入超过250V电压的电源。
 3. 严禁打开驱动器和电机的后盖。
 4. 使用前请详细阅读说明书。
 5. 严禁塑料外壳受力及受压。
1. Servo driver must connect to earth wire, otherwise will cause risk of electric shock.
2. Servo driver is strictly prohibited to connect with power over than 250 V voltage.
3. Prohibit to open the front and rear cover of the driver and motor.
4. Please read instructions carefully before use.
5. Prohibit plastic shell being applied heavy objects or excessive force.



警告 CAUTION



不要随便拆零件。
在有安全设施下进行操作。
在穿线、换梭心、机针及清扫等之
前先关掉电源停止缝纫。
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin and
needle, cleaning ect.

JACK 杰克

服务热线: 4008876858

E-mail: sales@chinajack.com

Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA

<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>


Número do documento: 24082218342496100000066260647

Aug 21, 2024 14:56
Num. 848fc71 - Pág. 12



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Num. 8
Aug 21, 2024, 15:07



交流伺服控制系统
AC SERVO CONTROL SYSTEM
额定电压: AC220V
频率: 50 / 60Hz
Rated Voltage: AC220V
frequency: 50 / 60Hz
额定功率: 550W
最大转速: 5000RPM
Rated Power: 550W
Max Speed: 5000RPM



危险
WARNING

1. 何種運動機件均應接地，否則有觸電危險。
2. 何種運動機件均應接地，否則有觸電危險。
3. 何種運動機件均應接地，否則有觸電危險。
4. 何種運動機件均應接地，否則有觸電危險。
5. 何種運動機件均應接地，否則有觸電危險。
1. Never touch any moving parts directly, otherwise will cause risk of electric shock.
2. Never touch any moving parts directly, otherwise will cause risk of electric shock.
3. Never touch any moving parts directly, otherwise will cause risk of electric shock.
4. Never touch any moving parts directly, otherwise will cause risk of electric shock.
5. Never touch any moving parts directly, otherwise will cause risk of electric shock.



警告
CAUTION
不要直接接觸運動機件，否則有觸電危險。
Do not touch any moving parts directly, otherwise will cause risk of electric shock.
不要直接接觸運動機件，否則有觸電危險。
Do not touch any moving parts directly, otherwise will cause risk of electric shock.



Assinado eletronicamente por: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Aug 21, 2024 15:08
Num. 848fc71 - Pag. 15



交流伺服控制系统
AC SERVO CONTROL SYSTEM

额定电压: AC220V
频率: 50 / 60Hz
Rated Voltage: AC220V
Frequency: 50 / 60Hz

额定功率: 550W
最大转速: 5000RPM
Rated Power: 550W
Max Speed: 5000RPM



危险
WARNING

1. 伺服驱动器必须接地, 否则有触电危险。
2. 伺服驱动器严禁接入超过250V电压的电源。
3. 严禁打开驱动器或电机的后盖。
4. 使用驱动器时必须佩戴绝缘手套。
5. 严禁带电检修及保养。

1. Servo driver must connect earth wire, otherwise will cause risk of electric shock.
2. Servo driver strictly prohibited to connect with power over than 250V.
3. Prohibited to open the front and rear cover of the driver and motor.
4. Please wear insulating gloves when using the driver and motor.
5. Prohibited driver and motor without being disassembled or maintained when power on.

警告
CAUTION



伺服驱动器



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Assinado eletronicamente por: FRED HENRIQUE OLIVEIRA DA SILVA - Juntado em: 22/08/2024 18:39:20 - 848fc71

交流伺服控制系统 AC SERVO CONTROL SYSTEM

额定电压: AC220V
频率: 50 / 60Hz
Rated Voltage: AC220V
Frequency: 50 / 60Hz


额定功率: 550W
最大转速: 5000RPM
Rated Power: 550W
Max Speed: 5000RPM



危险
WARNING

1. 伺服驱动器必须接地, 否则有触电危险。
2. 伺服驱动器严禁接入超过250V电压的电源。
3. 严禁打开驱动器和电机的后盖。
4. 使用前请详细阅读说明书。
5. 严禁超载和大力矩运行。

1. Servo driver must connect with wire, otherwise will cause risk of electric shock.
2. Servo driver strictly prohibited to connect with power over than 250V.
3. Forbidden to open the front and rear cover of the driver and motor.
4. Please read manual before starting work.
5. Prohibited operation shall bearing overload torque or excessive torque.



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA

<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>

Número do documento: 24082218342496100000066260647

Aug-21, 2024, 15:08
Num. 848fc71 - Pág. 18



Assinado eletronicamente. A Certificação Digital pertence a: FRED HENRIQUE OLIVEIRA DA SILVA
<http://pje.trt18.jus.br/primeirograu/Processo/ConsultaDocumento/listView.seam?nd=24082218342496100000066260647>
Número do documento: 24082218342496100000066260647

Aug 21, 2024, 15:08
Num. 848fc71

交流伺服控制系统 AC SERVO CONTROL SYSTEM

额定电压：AC220V

频率：50 / 60Hz

Rated Voltage: AC220V

Frequency: 50 / 60Hz

额定功率：550W

最大转速：5000RPM

Rated Power: 550W

Max Speed: 5000RPM



危险
WARNING

1. 伺服驱动器必须接地，否则有触电危险。
2. 伺服驱动器严禁接入超过250V电压的电源。
3. 严禁打开驱动器和电机的后盖。
4. 使用前请详细阅读说明书。
5. 严禁塑料外壳受力及受压。

1. Servo driver must connect earth wire, otherwise will cause risk of electric shock.
2. Servo driver strictly prohibit to connect with power over than 250V voltage.
3. Prohibited to open the front and rear cover of the driver and motor.
4. Please read instructions carefully before use.
5. Prohibited plastic shell being applied heavy objects or excessive force.



警告
CAUTION



不要随便拆零件。
在安全位置下进行操作。
在接线、换线、材料及清理之前
必须先断电并上锁。

Moving parts may cause harm.
Operate with safety device.
Turn off main switch before connecting
changing bodies and handle cleaning
etc.